



3408 Turnstone Drive Victoria BC V9C 0B4

Prepared For: TBA
Prepared By: David Fletcher #62502
Date: August 24th, 2020

SUMMARY	1	
EXTERIOR	3	
ROOF	9	
GARAGE	11	
HALLS and ENTRANCE	13	
LIVING SPACE	14	
FIREPLACE	17	
KITCHEN	18	
LAUNDRY ROOM	23	
BATHROOM Lower level	24	
BATHROOM Upper level, Main	26	
BEDROOM	29	
STAIRS	31	
ELECTRICAL	32	
HEATING	35	
PLUMBING	37	
STRUCTURE	39	
ATTIC	42	
CRAWLSPACE	44	
TRAILER	46	



SUMMARY

Client Name: TBA

Client Phone Number: +12508125472

Client Email: inspectorfletcher@gmail.com

Inspection Date: August 24th, 2020 Inspector: David Fletcher #62502

Phone Number: 250-812-5472

Email: inspectorfletcher@gmail.com

Water: ON Electricity: ON Gas: ON Oil: NA

Statement: This inspection is in accordance with the home inspector is association

of BC. It reflects only items that can be visually inspected. Items such as default in walls perimeter drainage, pool and spas, appliances, irrigation, fencing, built-in vacuums, septic systems, testing and verification of molds, testing and verification of asbestos based building materials, and water quality sampling are specifically excluded from the inspection. Homes built prior to 1993 have been known to contain

asbestos based building materials. ensure proper sampling precautions and verification is taken if there are plans to disturb or renovate the home. Inspection may be hindered due to storages or due

to owners request.

ITEMS OF NOTE

EXTERIOR

Driveway - Status: Acceptable, Minor settlement/crack noted near utility boxes at front of driveway. Recommendations: Keep drain free of debris, Monitor crack for any further movement.

Walks:2 - Status: Fall hazard areas noted along rock side at rear of home. Implications: Fall hazard. Recommendations: Use caution around area, especially for children.

Siding - Status: Minor cracking noted in select areas, Recently painted. Implications: Cosmetic. Recommendations: Monitor for any damages or loose boards, Ideally seal cracks, appeared some maintenance had been done.

Trim and Fascia - Status: Acceptable, Recently painted.

Stairs - Status: Missing Handrail, Missing Guardrail. Implications: Fall hazard. Recommendations: Use caution, consider improvements.

Exterior Structures - Status: Acceptable, Minor rot noted to top cap railing in lower patio area. Recommendations: Keep up with maintenance, minor repairs may be needed in upcoming seasons.



ROOF Roof - Status: Acceptable, Signs of previous moss growth.

Implications: Premature Deterioration. Recommendations: Treat and

clear roof surface of moss annually.

GARAGE Doors - Status: Acceptable, Minor damage noted, appears a door stop

may of been installed.

Auxiliary - Status: Not Inspected, Unknown if included in sale.

HALLS and ENTRANCE

Walls - Status: Acceptable, Signs of previous repair noted above

master bedroom door. Recommendations: Monitor.

LIVING SPACE Floor - Status: Acceptable, Minor UV staining noted.

FIREPLACE Flue - Status: Damaged screening noted at exhaust area. Implications:

Animal activity. Recommendations: Repair.

KITCHEN Electrical: 2 - Status: Capped/not installed.

Counter / Cabinet - Status: Acceptable, Showing some signs of wear.

Dishwasher - Status: Acceptable, Upgraded 2019.

BATHROOM Upper

level, Main

Doors Wood pocket door - Status: Acceptable, Does not latch/lock.

Implications: Privacy. Recommendations: Repair.

BATHROOM Upper

level, Main

Toilet - Status: Acceptable, Upgraded 2020.

BEDROOM Floor - Status: Acceptable, Appeared upgraded. Recommendations:

Minor deflection (squeeking) noted in master bedroom, monitor for any

changes.

STRUCTURE Foundation - Status: Typical settlement cracking. Implications: Minor

settlement at time of build. Recommendations: Monitor, Treat

perimeter for ants annually.

Posts / Pillars - Status: Acceptable, Not fully visible due to finishing.

Wall Structure - Status: No signs of major defect.

CRAWLSPACE Ventilation - Status: Acceptable, Vents appear blocked via insulation.

Implications: Poor ventilation, Recommend removing insulation

barriers in the spring.



Method of inspection: From the ground



Driveway:

Material / Type: Concrete

Description: Exposed Aggregate
Status: Acceptable, Minor settlement/crack noted near

utility boxes at front of driveway

Recommendations: Keep drain free of debris, Monitor crack for any further movement







Walks:

Material / Type: Gravel, Flag stone

Status: Acceptable





Walks:2:

Material / Type: Stone and gravel areas Status: Fall hazard areas noted along rock side at rear of home Implications: Fall hazard Recommendations: Use caution around area, especially for children





Siding:

Material / Type: Cementious Fibre Board

Status: Minor cracking noted in select areas, Recently

painted

Implications: Cosmetic

Recommendations: Monitor for any damages or loose

boards, Ideally seal cracks, appeared some

maintenance had been done





Trim and Fascia:

Material / Type: Wood

Status: Acceptable, Recently painted

Doors:

Material / Type: Glass windows, Metal clad Description: Front, With roll away bug screening

Status: Acceptable



Windows:

Material / Type: Vinyl Framed

Description: Double pane, Dated 2006



Stairs:

Material / Type: Wood, Pressure treated

Description: Deck stairs

Status: Missing Handrail, Missing Guardrail



Implications: Fall hazard

Recommendations: Use caution, consider

improvements



Soffit and Eaves:

Material / Type: Aluminium

Status: Acceptable

Recommendations: Monitor for wasp nesting



Exterior Structures:

Material / Type: Pressure treated wood

Description: Deck

Status: Acceptable, Minor rot noted to top cap railing in

lower patio area

Recommendations: Keep up with maintenance, minor repairs may be needed in upcoming seasons







Lighting/Electrical:

Material / Type: 110 Volt GFCI Protected, Surface

mounted lights Status: Acceptable Recommendations: GFCI reset is located near front of

home



Retaining Wall: Material / Type: Stone

Status: Acceptable

Recommendations: Monitor for invasive plant species, remove as needed



Auxiliary:

Description: Dryer Vent, Hose Bibb

Status: Acceptable

Vegetation:

Material / Type: Trees, Lawn, Gardens, Hedges

Status: Acceptable





Grading:

Material / Type: Flat, Slight slope

Status: Acceptable

Recommendations: Perimeter drains not inspected, consider further evaluation



ROOF

Method of inspection: Walking on the roof



Roof:

Material / Type: Fibreglass Shingle Status: Acceptable, Signs of previous moss growth

Implications: Premature Deterioration Recommendations: Treat and clear roof surface of moss annually





ROOF

Roof Flashing: Material / Type: Metal

Status: Acceptable

Recommendations: Keep drainage areas free of debris to avoid leaks



Gutters:

Material / Type: Aluminium Status: Acceptable

Roof Vents:

Material / Type: Metal Status: Acceptable

Plumbing Stack:

Material / Type: ABS, Rubber flashings

Status: Acceptable

Recommendations: Back gutter needs cleaning



GARAGE

Location: Attached, Single car



Garage Door:

Material / Type: Insulated Aluminium

Status: Acceptable

Garage Door Opener:

Material / Type: Mechanical Description: Chamberlain Status: Acceptable

Recommendations: Monitor for difference in chain length through hot/cold, adjust for optimal function





GARAGE

Doors:

Material / Type: To Interior

Description: Fire Rated, Metal clad

Status: Acceptable, Minor damage noted, appears a

door stop may of been installed



Floor:

Material / Type: Concrete Status: Acceptable

Walls / Ceiling:

Material / Type: Painted Status: Acceptable

Electrical:

Material / Type: 110 Volts A/C, Fluorescent lighting

Status: Acceptable

HVAC:

Material / Type: Electric baseboard, Side mounted

controls

Status: Acceptable

Auxiliary:

Material / Type: Vacuum system

Status: Not Inspected, Unknown if included in sale


Recommendations: Use sparingly in winter to avoid

freezing conditions in garage



HALLS and ENTRANCE





Floor:

Material / Type: Stone tiled entry

Status: Acceptable

Floor:2:

Material / Type: Carpet Status: Acceptable

Walls:

Material / Type: Painted

Status: Acceptable, Signs of previous repair noted

above master bedroom door

Recommendations: Monitor



Ceiling:

Material / Type: Textured Paint


Status: Acceptable

Electrical:

Material / Type: 110 Volt outlets, Standard lighting, Smoke and CO detector, Four way lighting switch



LIVING SPACE



Floor:

Material / Type: Engineered Hardwood Status: Acceptable, Minor UV staining noted



Walls:

Material / Type: Painted Status: Acceptable

Ceiling:

Material / Type: Textured Paint

Description: Vaulted Status: Acceptable

Doors:

Material / Type: Vinyl framed sliding glass



LIVING SPACE

Windows Double

pane:

Material / Type: Vinyl Framed Description: Double pane Status: Acceptable

Windows Double pane, Slider opening:

Material / Type: Vinyl Framed

Description: Double pane, Slider opening

Status: Acceptable



Closet:

Material / Type: Large, Understairs closet Description: Finished, With built in storage

Status: Acceptable



HVAC:

Material / Type: Electric baseboard



LIVING SPACE

Electrical:

Material / Type: 110 Volt outlets, Standard lighting,

Ceiling fan



FIREPLACE

Location: Living room



Fire box:

Material / Type: Gas log insert, With thermostatic

controlled fan

Description: Thermostat control

Status: Acceptable

Flue:

Material / Type: Side wall exhaust

Status: Damaged screening noted at exhaust area

Hearth:

Material / Type: Flush mounted stone tile

Status: Acceptable

Mantle:

Material / Type: Wood, Manufactured Fibre Board

Status: Acceptable

Recommendations: Service gas appliances every 1-2

years

Implications: Animal activity Recommendations: Repair





Floor:

Material / Type: Stone tile Status: Acceptable

Walls:

Material / Type: Painted Status: Acceptable

Ceiling:

Material / Type: Textured Paint

Status: Acceptable

Windows:

Material / Type: Vinyl Framed

Description: Double pane, Slider opening

Status: Acceptable



Closet:

Material / Type: Small single, Pantry



Electrical:

Material / Type: 110 Volt outlets, Standard lighting

Status: Acceptable

Implications: Shock hazard, Caution, non GFCI outlets next to sink, not required at time of construction Recommendations: Upgrade outlets next to sinks to GFCI type



Electrical:2:

Material / Type: Garborator circuit Status: Capped/not installed







Electrical:3:

Material / Type: Decommissioned circuit

Status: Acceptable



Counter / Cabinet:

Material / Type: Laminate Status: Acceptable, Showing some signs of wear





Kitchen Plumbing:

Material / Type: ABS drain, Brushed metal faucet, PEX Recommendations: Shut off for back yard hose Bibb is supply, Extendable spray nozzle, Anti hammering

Status: Acceptable

located under kitchen sink



Sink:

Material / Type: Anthracite Description: Double Status: Acceptable

Cooking **Appliance:**

Material / Type: Gas Description: Kitchenaid Status: Acceptable

Refrigerator:

Material / Type: Standard Description: Kitchenaid Status: Acceptable

Dishwasher:

Material / Type: Stainless Steel

Description: Bosch

Status: Acceptable, Upgraded 2019



Kitchen **Ventilation:**

Material / Type: Above stove

Status: Acceptable



Microwave:

Material / Type: Stand alone Description: Panasonic Status: Acceptable



LAUNDRY ROOM



Floor:

Material / Type: Stone tile Status: Acceptable

Walls:

Material / Type: Painted Status: Acceptable

Ceiling:

Material / Type: Painted Status: Acceptable

Doors:

Material / Type: Interior Description: Bi-fold closet door

Status: Acceptable

Electrical:

Material / Type: 110 Volt outlets, 220 Volt outlet

Status: Acceptable

Laundry Plumbing:

Material / Type: Stand pipe, Ball valve hose bib, Plastic

hoses

Status: Acceptable

Dryer Vent:

Material / Type: Rigid metal Description: Rigid metal Status: Acceptable

Appliances:

Material / Type: Dryer, Washer

Description: Electric, High efficiency, Maytag

Status: Acceptable

Recommendations: Caution, may block garage door

while open

Recommendations: Clean out dryer vent



BATHROOM Lower level

Location: Lower level



Floor:

Material / Type: Stone tile Status: Acceptable

Walls:

Material / Type: Painted Status: Acceptable

Ceiling:

Material / Type: Painted Status: Acceptable

Doors:

Material / Type: Interior Status: Acceptable

Windows:

Material / Type: Vinyl Framed

Description: Double pane, Double Hung opening

Status: Acceptable

HVAC:

Material / Type: Electric baseboard

Status: Acceptable

Electrical:

Material / Type: Standard lighting, 110 GFCI outlet,

Ventilation fan Status: Acceptable

Counter / Cabinet:

Material / Type: Laminate Status: Acceptable



BATHROOM Lower level

Bathroom Plumbing:

Material / Type: ABS drain, Chromed metal faucet,

PEX supply Description: Delta Status: Acceptable

Sink:

Material / Type: Porcelain Status: Acceptable

Toilet:

Material / Type: Standard, Upgraded

Description: ProFlo Status: Acceptable



BATHROOM Upper level, Main

Location: Upper level, Main



Floor:

Material / Type: Stone tile Status: Acceptable

Walls:

Material / Type: Painted Status: Acceptable

Ceiling:

Material / Type: Painted Status: Acceptable

Doors Hollow wood:

Material / Type: Interior Description: Hollow wood Status: Acceptable





Doors Wood pocket door:

Material / Type: Interior Description: Wood pocket door Status: Acceptable, Does not latch/lock Implications: Privacy Recommendations: Repair



Windows:

Material / Type: Vinyl Framed

Description: Double pane, Double Hung opening

Status: Acceptable

HVAC:

Material / Type: Wall mounted fan assisted electric

Status: Acceptable

Electrical:

Material / Type: Standard lighting, 110 GFCI outlet,

Ventilation fan Status: Acceptable

Closet:

Material / Type: Small single

Status: Acceptable

Counter / Cabinet:

Material / Type: Laminate Status: Acceptable

Bathroom Plumbing:

Material / Type: ABS drain, Chromed metal faucet,

PEX supply Status: Acceptable Recommendations: GFCI reset located in lower level

bathroom



BATHROOM Upper level, Main

Sink:

Material / Type: Porcelain Status: Acceptable

Toilet:

Material / Type: Standard Description: Pro Flo

Status: Acceptable, Upgraded 2020

Shower / Tub:

Material / Type: Plastic, Acrylic finish Description: Bathtub with shower





BEDROOM

Location: Master, Second, Third







Floor:

Material / Type: Carpet

Status: Acceptable, Appeared upgraded

Walls:

Material / Type: Painted Status: Acceptable

Ceiling:

Material / Type: Textured Paint

Status: Acceptable

Doors:

Material / Type: Interior Status: Acceptable

Windows:

Material / Type: Vinyl Framed

Description: Double pane, Slider opening

Status: Acceptable

Recommendations: Minor deflection (squeeking) noted

in master bedroom, monitor for any changes



BEDROOM

Closet:

Material / Type: Large, 2x Large closets in Master

Status: Acceptable



HVAC:

Material / Type: Electric baseboard

Status: Acceptable

Electrical:

Material / Type: 110 Volt outlets, Standard lighting,

Ceiling fan in master and second bedroom



STAIRS Location: Main



Handrail/Guardrail:

Material / Type: Wood, Wood spindles

Status: Acceptable

Floor:

Material / Type: Carpet Status: Acceptable

Walls:

Material / Type: Painted Status: Acceptable

Electrical:

Material / Type: Standard lighting, Three way lighting

switch



ELECTRICAL

Location: Garage

Service Wires / **Entrance:**

Material / Type: Stranded aluminum Description: 125 Amp, Underground service

Status: Acceptable

Electrical Panel:

Material / Type: Square D Status: Acceptable









ELECTRICAL

Main power Shut

Off:


Material / Type: 125 Amp Description: Located at panel



Conductor Cables:

Material / Type: Non-metallic sheathed cable

Description: Copper Status: Acceptable



Breakers:

Material / Type: Copper and Aluminium rated

Arc Fault Circuit Interrupters:

Material / Type: Bedroom circuits



ELECTRICAL

Panel Bonding:
Material / Type: Bonding screw in place





HEATING

Location: Room by Room

Type:

Material / Type: Electric Baseboard

Status: Acceptable



Thermostat Wall mounted:

Material / Type: Standard Location: Wall mounted Status: Acceptable





HEATING

Thermostat Wall mounted:

Material / Type: Programmable, For main living area

Location: Wall mounted Status: Acceptable



Heating System Make:

Material / Type: Dimplex Status: Acceptable



Fuel Type / Exhaust:

Material / Type: Electricity Status: Acceptable

Distribution:

Material / Type: Convection baseboard heaters

Status: Acceptable

Recommendations: Ensure proper 1" clearance from cords and combustibles

Page 36



PLUMBING

Shut Off Location: Garage





Main Water Supply:

Material / Type: PEX Status: Acceptable

Water lines:

Material / Type: PEX Status: Acceptable

Drain Waste Plumbing:

Material / Type: ABS Status: Acceptable

Vent Plumbing:

Material / Type: ABS Status: Acceptable

Gas/Oil Supply Plumbing:

Gas Shut Off Location: At meter Material / Type: Steel, Copper

Status: Acceptable



PLUMBING

Hot Water Heater:

Water Heater Location: Garage

Material / Type: Gas, Naturally aspirated dual vent Age: Typical lifespan 8-12 years, Manufactured in

2015

Status: Acceptable

Recommendations: Budget for upcoming tank replacement in approximately 3 years









STRUCTURE

Method of inspection: Partially Visible



Frame Work:

Material / Type: Wood frame, 2x6 wall construction

Status: Acceptable



STRUCTURE

Foundation:

Material / Type: Poured Concrete Status: Typical settlement cracking

Implications: Minor settlement at time of build Recommendations: Monitor, Treat perimeter for ants annually







STRUCTURE

Floor Beams:

Material / Type: Solid Wood, 2x10

Status: Acceptable

Posts / Pillars:

Material / Type: Solid wood, Bonded wood

Status: Acceptable, Not fully visible due to finishing

Wall Structure:

Material / Type: Wood framed, Not visible due to

finishing

Status: No signs of major defect



ATTIC

Method of inspection: From Attic Hatch Access Location: 3rd bedroom ceiling





Attic Hatch:

Material / Type: Drywall, With fibreglass batt insulation

Status: Acceptable

Insulation:

Material / Type: Blown in cellulose Description: Approx depth 14"+

Status: Acceptable

Ventilation:

Material / Type: Roof and soffit ventilation

Status: Acceptable

Roof / Ceiling

Frame:

Material / Type: 2x4 truss Status: Acceptable



ATTIC

Roof Sheathing:

Material / Type: Oriented Strand Board (OSB)

Status: Acceptable



Ceiling vapour barrier:

Material / Type: Poly vinyl sheeting Status: Acceptable

Ventilation connections:

Material / Type: Insulated ducting

Status: Acceptable






CRAWLSPACE

Method of inspection: In the crawlspace, Limited due to storage

Location: Hatch in garage wall









Floor / Moisture

Barrier:

Material / Type: Concrete skim coat Status: Acceptable

Perimeter walls:

Material / Type: Concrete Status: Acceptable

Electrical:

Material / Type: Lighting Status: Acceptable




CRAWLSPACE

Heat Source:

Material / Type: Baseboard heater Description: Thermostat control

Status: Acceptable

Recommendations: Use sparingly during winter for convection air movement and to prevent freezing conditions in crawlspace



Insulation:

Material / Type: Styrofoam board

Status: Acceptable

Ventilation:

Material / Type: Vents Status: Acceptable, Vents appear blocked via

insulation

Implications: Poor ventilation, Recommend removing

insulation barriers in the spring





Island Home Inspection 3408 Turnstone Drive V9C 0B4